

### CASE STUDY:

Location: Hurst, TX




System: Carvin L250 with Waterway two-speed pump; 1- ½" PVC pipe

Pool: Above Ground; 18,536 gallons

Problem(s): "Pool not clearing; spending ~100's of dollars in chemicals every week".

"Lots of fine silt in the air from nearby land development"

Solution: Slow the pump to the lower speed, change filter media from BIÜ to Sanž



"I think we fixed my problem! Thank you so much for taking time to confirm my research/decision to run pump on low. And I learned a lot more about pool hydraulics from you too. I don't know that I've ever experienced better customer service! Thank you!" ~ pool owner – Hurst, TX



"1 week (with daily rain) with correct amt of Sanž filter balls... water is crystal clear! Unbelievable!! If you could understand how freakin frustrating and expensive this pool was for me this summer, you'd understand the depth of my satisfaction and gratitude! Thanks again!! " ~ pool owner – Hurst, TX